



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

1027  
RECEIVED  
DEC 05 1991  
0016 DIVISION OF  
OIL GAS & MINING

## INSPECTION REPORT

Permit No. ACT/007/005 Inspection Date: November 13-15, 1991  
 Permittee and/or Operators Name: Utah Fuel Company  
 Business Address: P.O. Box 719  
 City: Helper State: Utah Zip: 84526  
 Mine Name: Skyline Mine County: Carbon State: Utah  
 Type of Mining Activity: Underground XX Surface Other  
 Company Official (s): Keith Zobell  
 State Officials (s): Stephen J. Demczak, Gary Fritz (OSM)  
 Time of Inspection: 9:00 (X)a.m. ( )p.m. to 3:30 ( )a.m. (X)p.m.  
 Partial Complete: XX Weather Conditions: Snow/Teens  
 Acreage: Permitted 4,834 Disturbed 62.5 Regraded 0  
 Seeded 0 Bonded 62.5 Date of Last Inspection: October 25, 1991  
 Enforcement Action: None

## COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	NOTES
1. PERMITS	( X )	( )	( )	( X )
2. SIGNS AND MARKERS	( X )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( X )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( X )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( X )	( )	( )	( )
5. EXPLOSIVES	( X )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( X )	( )	( )	( )
7. COAL PROCESSING WASTE	( X )	( )	( )	( )
8. NONCOAL WASTE	( X )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( X )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( X )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( X )	( )	( )	( )
12. BACKFILLING AND GRADING	( X )	( )	( )	( )
13. REVEGETATION	( X )	( )	( )	( )
14. SUBSIDENCE CONTROL	( X )	( )	( )	( )
15. CESSATION OF OPERATIONS	( X )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( X )	( )	( )	( )
b. DRAINAGE CONTROLS	( X )	( )	( )	( )
c. SURFACING	( X )	( )	( )	( )
d. MAINTENANCE	( X )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( X )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( X )	( )	( )	( )
19. AVS Check	( X )	( )	( )	( X )

INSPECTION REPORT COMMENTS  
(continuation sheet)

Page 2 of 2

Permit No. ACT/007/005 Inspection Date November 13-15, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

- a. Utah Fuel Company (Skyline Mine) has been approved to build a truck shed/concrete scale as of November 6, 1991. Construction was observed on the above approval during inspection.
- b. The annual and quarterly reports on the refuge pile were viewed. The reports were certified by a registered P.E. Additional information on future reports should be submitted for easier clarification of status of the pile.
- c. The sediment pond inspection reports were reviewed and met the requirements of the regulations. The Division will receive a Ten Day Letter from OSM concerning the requirements of a sediment pond located at the mine site at Skyline. Presently the sediment pond has one culvert spillway which may not comply with the regulations.
- d. The liability insurance was reviewed during inspection. The insurance policy was found to be in compliance.

4a. Diversions -

The diversion ditches were inspected showing no sign of failure or blockage.

4c. Sediment Ponds and Impoundments -

The upper sediment pond was being cleaned out during inspection. The truck loadout pond was partially filled with water but was not discharging.

19. AVS Check -

An AVS check was made on site. All information was accurate.

Copy of report:

Mailed to: Utah Fuel Company

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO

Inspector's Signature and Number: Stephen J. Demczak #39

Date: December 3, 1991

Stephen J. Demczak